

33 years service to canmakers

... the value is in the detail

UNCOATED SHEETS ARE **BAD NEWS**

Uncoated or partially coated sheets may lead to line stops, HFIs, lost production, blunt press tooling and excess scrap, or even result in rusty cans, leaking product and customer complaints. **Sheet coating errors lose time and money and could cost you your reputation.**

NOW FOR THE GOOD NEWS

Sencon's sensors for detecting some of the chief causes of uncoated or partially coated can stock are completely self adjusting, 'fit and forget' products.

No set-up • No adjustment
No control boxes • No programming
No risk of wrong settings • No doubts



NORTH, CENTRAL & SOUTH
 AMERICA
 Telephone: +1 708 496 3100
sales@sencon.com

EUROPE • MIDDLE EAST • ASIA
 Telephone: +44 1905 827800
sales@sencon.co.uk

FRANCE • SPAIN
 France, tél: +33 176 641 287
 Espagne, tel: +34 937 549 526
info@sencon.eu